An integral Part of Your Company

FULL SPECTRUM ANALYTICS IN C.

FSA Ticket # 7,331 Workorder # 7209 Region: F4 Vendor Ref # 12/12/2017

www.fsaservice.com/forms/Warranty.pdf

SITE LOCATION			BILL TO:		
City of Scottsdale, Police Department			Full Spectrum		
7601 East McKellips Road, Scottsdale, AZ 85257					
Mr. Allan Kosecki, pkosecki@scottsdaleaz.g		OV			
Service Rep: Galvez, Joe		Service Type: Repair		Quality Level: Standard	
Billing Type: Non-Billable		Payment Method: Service Contract		PO#: N/A	
System ID	Manufactur	er	Model		Serial#
GC w/ HS					
Additional Instruments	Agilent 7890 GC S/N US14173023				

PROBLEM DESCRIPTION:

1 of 2 FIDs on the GC has an abnormally high signal.

WORK PERFORMED:

Observed a normal reading on one FID and an extremely high signal on the other. Disassembled the FID detector. Cleaned the FID jet and collector. Re-assembled the detector and repositioned the potentiometer. Powered on the instrument. Signal was significantly lower and continued to decrease as the system heated to their respective set points. System is operating properly.

Parts Total:

HOURS	RATE	TOTAL	
Labor Hours: 2.0	Labor Rate: \$300.00	Labor Total:	\$600.00
Travel Hours: 2.0	Travel Rate: \$300.00	Travel Total:	\$600.00
	Extended Travel: \$0.00	Misc. S&H:	\$0.00
		Total Labor:	\$1,200.00
	NOT AN INVOICE, TAXES NOT	Report Total:	\$1,200.00
~i:72:100~	<u>INCLUDED</u>	Credit Amount:	\$1,200.00
		Balance Due:	\$0.00

1252 Quarry Lane * Pleasanton * CA 94566 * 800-795-6357 * FAX: 925-485-9018