

www.fsaservice.com/forms/warranty.pdf

[How was your experience with Full Spectrum?](#)



LOCATION		SITE	BILL TO:	
City of Scottsdale, Police Department 7601 East McKellips Road, Scottsdale, AZ 85257 United States Mr. Allan Kosecki, pkosecki@scottsdaleaz.gov			Customer	
Service Rep: Hong, Ryan		Service Type: PM		Quality Level: Standard
Billing Type: Non-Billable		Payment Method: Service Contract		PO#: N/A
System ID	Manufacturer	Model		Serial#
GC w/ HS	Agilent	G3440A		CN14160045
Additional Instruments				
PROBLEM DESCRIPTION:				
PM				
WORK PERFORMED:				
Performed annual PM on the GC/HS system. Replaced sample loop and sampling needle. Performed tray offset calibration. Performed system decay and leak test, successfully. Checked the GC for leaks and checked flows for the front and rear detectors. Checked oven motor flapper for proper operation. Dusted off the equipment and cooling fans. Confirmed detector signal was within historical values for both front and back detectors. The system is operational.				

FSA Part# (Inventory)	Description (manual)	Qty	Price Each	Total
AG-7697-6005	Sample loop, headspace, 1.00 mL, inert	1	\$499.00	\$499.00
AG-7697-1010	Agilent 7697A Sample probe, deactivated SN1030	1	\$499.00	\$499.00
GCHS-PM-LABOR	GC Headspace PM Labor	1	\$684.00	\$684.00

Parts Total: \$1682.00

HOURS	RATE	TOTAL	
Labor Hours: 1.0	Labor Rate: \$0	Labor Total:	\$0
Travel Hours: 0.0	Travel Rate: \$0	Travel Total:	\$0
	Extended Travel: \$0	Misc. S&H:	\$0.00
	NOT AN INVOICE, TAXES NOT INCLUDED	Total Labor:	\$0
		Report Total:	\$1,682.00
		Credit Amount:	\$1682.00
		Balance Due:	\$0.00