

An Integral Part of Your Company

FULL SPECTRUM
ANALYTICS INC.

FSA Ticket # 5,379
Workorder # 5296
Region: F4
Vendor Ref #

www.fsaservice.com/forms/Warranty.pdf

SITE LOCATION		BILL TO:	
City of Scottsdale, Police Department Mr. Allan Kosecki, pkosecki@scottsdaleaz.gov 7601 East McKellips Road, Scottsdale, AZ 85257		Full Spectrum	
Service Rep: Galvez, Joe	Service Type: PM	Quality Level: Standard	
Billing Type: Non-Billable	Payment Method: Service Contract	PO#:	
System ID	Manufacturer	Model	Serial#
GC w/ HS			
Additional Instruments	7697A Headspace S/N CN14160045		
PROBLEM DESCRIPTION:			
7697 Headspace Annual Preventative Maintenance			
WORK PERFORMED:			
Turned off H2 carrier gas and lowered the temperature to the needle and valve. Changed the headspace sample loop and sampling needle. Reassembled the unit and turned the carrier gas back on. Checked for any leaks and system was able to maintain pressure. Ran a test sample. System is operating properly.			

FSA Part# (Inventory)	Description (manual)	Qty	Price Each	Total
	7697 Sample Loop (1mL)	1	\$432.00	\$432.00
	7697 Sample Probe	1	\$497.00	\$497.00

Parts Total: \$929.00

Onsite Date	Start Time	End Time	Break Hours	Onsite Hours
8/7/2017	10:00 am	12:00 pm		2.0

Total Onsite: 2.0

HOURS	RATE	TOTAL
Labor Hours: 2.0	Labor Rate: \$300.00	Labor Total: \$600.00
Travel Hours: 2.0	Travel Rate: \$300.00	Travel Total: \$600.00
	Extended Travel: \$0.00	Misc. S&H: \$0.00
		Total Labor: \$1,200.00
		Report Total: \$2,129.00
		Credit Amount: \$2,129.00
		Balance Due: \$0.00

NOT AN INVOICE, TAXES NOT INCLUDED